



Zig Replacement Information

| Replacement Chargers | | |
|---|--|---------------------------------------|
| Old charger | Replacement charger | |
| TX2000 | Replace with an X70 | |
| X2 | Replace with an X70 | |
| X3 | Replace with an X70 | |
| X7 | Replace with an X70 | |
| DCU15 & 3 | Replace with an X70 | |
| | | |
| X8 | Replace with an X80 | |
| X90 | Replace with an X80 | |
| | | |
| Power master has an X70 fitted the unit can be returned to ZIG for repair £150+p&p=vat | | |
| | | |
| CF4 or CF6 | Replace with a CF8 | |
| | | |
| CF2000 | Replace with a CF9 slight difference in size | Zig can repair CF2000 phone for quote |
| | | |
| WS500 | Repair only | |
| | | |
| Old control panels that are not still manufactured, we may be able to repair phone for quote 01482 868632 or 01482 880044 email info@olearymotorhomes.co.uk | | |